



CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" Ⓜ FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.

0.281 [7.14]- 4 HOLES IN PLAIN RACE  
 0.281 [7.14]- 4 HOLES IN LOCKING RACE

Ⓜ 0.203 [5.16] 4-HOLES IN PLAIN RACE



THERE MAY BE 2 TO 4 BALLS LEFT OUT DUE TO MANUFACTURING PROCESS.

Ⓜ

Ⓜ

Ⓜ 0.750 [19.05] DIA. TWO HOLES IN LOCKING RACE